

# GLP Firmware Change Log



GLP Twyn Firmware Log V0.7.0 - 6 May 2026 Rev4

Below you will find the history of all fixture firmware versions since the release of the device. Please note the respective information on functional changes, extensions, optimizations, etc. Even if it is our goal to develop firmware updates without relevant performance changes, it can always happen that optimizations or bug fixes can affect the device performance. Please read the note on "INFO" as a matter of urgency.

We strongly advise that firmware updates be carried out on individual replacement devices first. Likewise, updates should never be carried out shortly before an important use of the device. If in doubt, speak to your GLP Service Team.

<p>06 May 2026 / <b>Main changes from to V0.6.0 (BL3.4.1) to V0.7.0</b></p> <p>If the original version on the fixture is 0.6.0 (BL3.4.1) an update only via mesh is possible. Otherwise an iQ.Tool is needed for the Bootloader update.</p>	
FEATURES	na
Bug Fixes	Fixed a bug in the fan controller.
UPDATE PROCESS	<p><b>1. If necessary, first update the bootloader to V3.4.1 with iQ.Service and an iQ.Tool</b>, daisy chained via DMX/XLR. ( if a bootloader update is available the app will automatically recommend this update)</p> <p>The display could go off during this step. Please wait the 5 minutes timer running in the app for the internal firmware distribution, until the app asks you to proceed with step 2.</p> <p><b>2. Main Software Update V0.7.0 via iQ.Service &gt; iQ.Tool</b>, daisy chained via DMX / XLR, or iQ.Mesh.</p> <p>Choose the firmware which the app will show automatically. Once the main software is transferred and the app has finished, the fixtures could might need another minute for internal firmware distribution. Also an error can show up during a calibration upload.</p> <div style="border: 1px solid #ccc; padding: 5px; margin-top: 10px;"> <p><b>i</b> <b>If you loose power during the update</b>, don´t worry you can start step 1 or 2 manually at any time. Just with the bootloader programmed on the fixture only, the fixture will not show up automatically in the app, and the display can stay off. For step 2, select in the upper right toolbox: &gt; Fixture Update &gt; Manual Update &gt; Twyn and then the desired firmware. It will need about 4 minutes.</p> </div> <div style="border: 1px solid #ccc; padding: 5px; margin-top: 10px;"> <p><b>i</b> <b>If an iQ.Mesh update is needed, set the input protocol to iQ.Mesh.</b> <b>You can do this easily via the iQ.Service Tools (upper right toolbox)</b> &gt; RDM Manager &gt; Set to iQ.Mesh. Once set to iQ.Mesh you have to leave the iQ.Tool ( upper left: &lt; ) Scan for fixtures and update all fixtures to the latest <b>iQ.Mesh version 5.6.3</b>, or later After this a creative config update could follow.</p> <p>If you want to work with the fixtures via DMX afterwards, do not forget to change the input now back to DMX. RDM Manager &gt; Set to DMX.</p> </div>
INFO	<p>Twyn Version 0.7.0 ; Bootloader V3.4.1 iQ.Service Version 2.7.3, or later. iQ.Mesh Version 6.0.33, or later.</p>

# GLP Firmware Change Log

GLP Twyn Firmware Log V0.7.0 - 6 May 2026 Rev4



27 Jan 2026 / **V0.4.1-alpha (BL3.2.0)**

FEATURES	
	First Fieldtest release for internal use and demos

# GLP Firmware Change Log

GLP Twyn Firmware Log V0.7.0 - 6 May 2026 Rev4

