

GLP Firmware Change Log

Fusion Stick FS16Z / Fusion Stick FS16Z Firmware Log V1011 / 04/13/2023



Below you will find the history of all fixture firmware versions since the release of the device. Please note the respective information on functional changes, extensions, optimizations, etc. Even if it is our goal to develop firmware updates without relevant performance changes, it can always happen that optimizations or bug fixes can affect the device performance. Please read the note on "INFO" as a matter of urgency.

We strongly advise that firmware updates be carried out on individual replacement devices first.


Likewise, updates should never be carried out shortly before an important use of the device. If in doubt, speak to your GLP Service Team.

- [21 Mar 2023 / Main changes from V1009 to V1011](#)
- [29 Nov 2022 / Main changes from V1006 to V1009](#)

21 Mar 2023 / Main changes from V1009 to V1011

IMPROVEMENTS	<ul style="list-style-type: none">• Added RDM Factory Defaults
UPDATE PROCESS	<p>Update via Fusion Stick PC Update Software V103 via USB to XLR Connector item code 4930108: "Firmware Updater for Fusion FS10/ FS20/ FP7/FS16Z"</p> <p>Please make sure that no other DMX receivers or consoles are active on the line and fixtures Control Protocol is set to DMX All fixture settings will be reset to factory defaults after the main application update</p>
VERSION DETAILS	STICK_FS_16Z_XLR_V1011.FSN

29 Nov 2022 / Main changes from V1006 to V1009

BUG FIXES	<ul style="list-style-type: none">• Fixed: LED Inverse and Zoom inverse function
UPDATE PROCESS	<ul style="list-style-type: none">• Update via Fusion Stick Updater V1.03 <p>The fixtures can be updated daisy chain via DMX/RS485 USB to DMX Adapter. Please make sure that no other DMX receivers or consoles are active on the line and fixtures Control Protocol is set to DMX</p>
INFO	 This update is show critical as dimming, colormix and shutter behavior is changed

No responsibility taken for misprints, errors and technical changes.

Technical data is subject to change without notice as a result of product modification.

GLP German Light Products GmbH, Industriestrasse 2, 76307 Karlsbad, Germany, Managing Director: Udo Künzler

GLP Firmware Change Log

Fusion Stick FS16Z / Fusion Stick FS16Z Firmware Log V1011 / 04/13/2023



VERSION DETAILS	STICK_FS_16Z_XLR_V1009.FSN
-----------------	----------------------------